

EN

**INSTRUCTIONS FOR USE**

**Read and follow these instructions carefully!**

Users need to assess the risks at work and check that the product is suitable for them. The manufacturer assumes no responsibility for the use of the product against risks other than those mentioned and / or without following these instructions.

**Performances:**

The protective equipment is designed to comply with the provisions of Regulation (EU) 2016/425 of the European Parliament and of the Council and the essential health and safety requirements corresponding to the intended field of use for category I PPE, in accordance with the specifications of the standard: EN ISO 13688: 2013 - Protective clothing. General requirements

**Areas of use:**

Protective equipment of simple design for the protection of the body against minor risks - mechanical actions with superficial effects, atmospheric agents that are neither exceptional nor extreme - in normal environments, without potentially explosive atmosphere, which do not require other specific protective equipment, e.g. : construction, wood industry, transports, mechanical workshops, locksmith.

**Instructions for use:**

Before each use, the user must check the clothing for visible damage; damaged clothing must not be used!


The product must be closed and fitted to the body while wearing, in order to avoid the risk of being caught with tools operated by the user or the risk of entrapment by moving machine parts.

**Storage:**

Store in dry, well-ventilated rooms, away from moisture and direct sunlight, with temperatures between 5 and 25 ° C.

**Marking:** The label is sewn inside the garment visibly positioned.

Label template:



**Maintenance and cleaning:** Strictly observe the icons mentioned on the product label!

LEGEND					
	Wash at maximum 30 °C		Do not tread		Centrifugal drying at low temperature
	Wash at maximum 40 °C		Ironing at low temperatures, maximum 110 °C		Centrifugal drying at moderate temperature
	Washing cycle for synthetic clothing, at maximum 40 °C		Ironing at moderate temperatures, maximum 150 °C		Do not spin dry
	Wash at maximum 60 °C		Ironing at high temperatures, maximum 200 °C		Do not dry clean
	Manual washing		Do not use bleach		It can be cleaned with perchlorethylene, hydrocarbons, solvents R113 and R11
	Washing prohibited		Bleaching based on chlorine and oxygen allowed		

The EU Declaration of Conformity can be accessed at: <https://magazin.renania.ro/>



+40 265 264 817